


Mini pneumacit crane




Sthrom Gradions













.







.
































10 4x 2x


....





...














.







....

Pneumatic hoses



There are about 1m Pneumatic Tubes, Cut by yourself



4x 2780, 11



2x 32054, 11



2x 3705, 11




1x 18938, 11

1x 11214, 85





2x 47222, 85



1x 18942, 85



1x 3713, 86



4x 60483, 86



2x 32013, 86



6x 6536, 86



1x 41678, 86




2x 6632, 86



2x 32556, 86




2x 32017, 86




3x 32073, 86




2x 32250, 86




2x 32526, 86



1x 18939, 86



1x 32525, 86



1x 18940, 86



4x 32062, 5




2x 24316, 88



6x 6558, 7

1x 2793c01, 3



1x 21828c01, 3